

N00204.AR.002342
NAS PENSACOLA
5090.3a

ELECTRONIC CORRESPONDENCE REGARDING LANDFILL AREA MONITORING WELLS
SITE 1 NAS PENSACOLA FL
11/21/1997
ENSAFE/ALLEN AND HOSHALL

To: William H Gates@Code 18,William J Hill@Code 18
From: "MICHAEL KEETHLER" <mkeethler@ensafe.com>
Cc:
Bcc:
Subject: Site 1 RD
Attachment:
Date: 11/21/97 11:00 AM

I talked with Greg Brown and he agreed that since Site 1 is not a new landfill than we shouldn't have to have monitoring wells every 500' as required for a new landfill. He said as long as we had the different flow directions covered and could support how many wells we were monitoring than that would be sufficient. As I interpret what he said this also included the requirement to have the downgradient wells also. This means we probably don't need to install a bunch of new wells if any.

He also suggested that we monitor quarterly for the first year and than have a decision point and fall back to semi or annual monitoring. We probably will choose annual and let them make us to semi if they are going to. I think that we may have the latitude also on what we are going to monitor for, maybe everything for the first year and than only what exceedances we had after that or maybe only the detections the first year and than only exceedances. I am going to talk to Claire about this. Let me know what your preferences are.

MICHAEL KEETHLER

EnSafe Inc.

Tel: 901-372-7962

Fax: 901-372-2454

Internet Address: mkeethler@ensafe.com

Home Page: <http://www.ensafe.com>
